

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 370 Const Calendar Day: 82 Date: 25-Aug-2012 Saturday Inspector Name: Wright, Doug Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 06:50 AM 03:30 PM **Break:** 00:30 **Over Time:** 08:00

Federal ID: Location:

Reviewer: Schmitt, Alex Approved Date: Status: Submit

Weather

Temperature 7 AM 12 PM 4PM Precipitation Condition

Working Day 🗸 If no, explain:

Diary:

Load Transfer Activities

Overview of Cable work today:

The following work was ongoing today on the Cable:

- Misc prep work for load transfer (LT) suspender jacking
- Cleaning & paint repairing the suspender bracket bottom flanges

I was inspecting Gary Anderson's crew on LT prep work at the suspender jacking brackets & other misc work. See below for a list of labor for these crews, & for details of the work performed. Also, I intermittently inspected the cleaning & painting of the suspender bracket bottom flanges.

- I arrived at the pier 7 office at 06:50, & was on the bridge at 07:00.
- From 07:00 until 08:30, Gary's crew was installing access platforms at the phase-3 suspender bracket locations.
- From 08:30 until the end of the shift, Gary's crew was installing jacking chairs at the phase-3 suspender bracket locations.
- From 07:00 until 12:00, the paint crew was cleaning & prepping the suspender bracket bottom flanges at PPs 10S, 14S, 18S, 22S, & 26S. They cleaned the bottom flanges & inside the anchor rod hole (including the seam between the bottom flange & the bearing plate). METS NACE inspector Charlie Stewart was the primary inspector on this work. See his diary for additional details. I only intermittently checked on the painting operation when Charlie was busy elsewhere on the bridge.
- From 12:30 until the end of the shift, the paint crew was added one coat of organic zinc primer to the anchor rod holes.
- Also intermittently throughout the shift, I did spot checks on the seams between the bottom flanges & the bearing plates on the South side. I used a 0.152mm feeler gauge to check to see if the plates were brought into firm contact. If there are not, then they are required to be sealed by caulking. I checked 42 holes at 21 different suspender bracket locations. Of the 42 seams checked, 24 of them were not in firm contact & the feeler gauge could be inserted between the plates. These seams will require caulking after they have received a paint repair. I emailed Roman Granados with this information on the South side to be combined with the information that he gathered on the North side suspender brackets.
- At 15:00, I left the bridge.
- From 15:10 until 15:30, I wrote my diary for the day, checked email, & submitted my timesheet for the week.

 04-0120F4
 Bid Item:
 067
 C-SUS-BGS.067
 Attach BG Lifts to Suspenders

 AMERICAN BRIDGE/FLUOR, A JV

 Labor

 Trade
 Class
 Name
 RT Hrs. OT Hrs. DT Hrs. Total. Remarks
 Dispute



Page 1 of 2

Run date 22-Nov-14

3:55 AM

Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contractor: AM	ERICAN BRIDG	E/FLUOR, A JV					
Ironworker	JNM	RENE ESQUIVEL	0.00	8.00	0.00	8.00	
Ironworker	JNM	LONNY CANDELARIA	0.00	8.00	0.00	8.00	
Ironworker	FOR	MATTHEW HOLT	0.00	8.00	0.00	8.00	
Ironworker	APP	ETHAN KENT	0.00	8.00	0.00	8.00	
Ironworker	JNM	JOSE ALFARO	0.00	8.00	0.00	8.00	
Ironworker	JNM	STANLEY DALIE	0.00	8.00	0.00	8.00	
Ironworker	JNM	HAYES BATISTE	0.00	8.00	0.00	8.00	

Attachment



0.152mm feeler gauge in between suspoender bracket bottom flange & bearing plate - These seams will be caulked.

